

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program June 17, 2013

	De Way		
Reviewed: _	11110		

Mine Name: Reef Mine	Permit Number: S/015/0094	
Operator Name: Castle Valley Stone	Inspection Date: June 11, 2013	
Inspector(s): Wayne Western, Mike Bradely	Time: 12:25 – 1:15 pm	
Other Participants: none	Mine Status: ACT	
Weather Condition: Clear sky 77 degrees	Last Inspection: June 18, 2013	
Bond Renewal Date: August 3, 2012	Bond Amount: \$25,200.00	
Surface Ownership: SITLA	Mineral Ownership: SITLA	
Last Year of Production: 2011 annual report for 2012 NA	Acreage: 5 acres	

	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer,			
2.	Bond/Bond Release	\boxtimes		
3.	Annual Fees			
4.	Annual Report		\boxtimes	
5.	Public Safety (shafts, adits, trash, signs, highwalls)			
6.	Protection of Drainages / Erosion Control			
7.	Deleterious Material			
8.	Roads (maintenance, surfacing, dust control, safety)			
9.	Concurrent Reclamation			
10.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
11.	Water Impoundments			
12.	Soils			
13.	Re-vegetation			
14.	Air Quality			
15.	Other			

Purpose of Inspection:

To determine the disturbed area.

Inspection Summary:

The Division measured the disturbed area and determined that the disturbed areas was 25.6 acres. The site is permitted for 5 acres. The Division will issue a cessation order until the issues have been resolved.

The site was active. See photos. The Operator was using trackhoes, loaders and a rock splitter. Some workers were using hand tools to dress stones.

Overburden was placed in drainages along the edge of the disturbed areas.

Inspection Date: June 11, 2013 Page 2 of 4 S/015/0094

The annual report for 2012 was not submitted.

The bond is inadequate to reclaim the site in case of a forfeiture.

Conclusions and Recommendations:

The Division will issue a cessation order until the issue of mining outside the permit boundary has been resolved.

by Unter


Directions to Site:

Inspector's Signature

WHW:

cc: (OPERATOR)
John Blake, SITLA

O:\M015-Emery\S0150094-Reef\inspections\insp-06112013.doc




Stockpiles and loading area.



Working areas and storage

Inspection Date: June 11, 2013 Page 4 of 4 S/015/0094



Waste material pushed into drainage



Working areas